

By the parenthesis
void setup() ? (prints must succeed)
What signs must succeed

prints the value of the variable A
on the serial monitor

11(2) = ?

Serial.print('A');

3

delay(100)
What are A0, A1, A2, ...?


476

the function has no numerical output

Digital ports
;

Serial data
...

Serial.begin(9600);



`Serial.println("A");`

Writes *A* on the serial monitor
Waits 100 milliseconds before continuing

`Serial.print(A)`

What sign ends a line in your code?
decimal number

SCL
SDA

sets serial data communication to 9600 bit/sec

Analogue output ports

What are D0, D1, D2, ...?

`Serial.print(A)`

Number of milliseconds elapsed since start or reset

`int`

How can you recognise a function?

integer

`void`

? = (2)0011101110
`float`

Writes *A* on the serial monitor and get ready to write on a new line

`millis()`