
# ROADSCANNERS

# **BEYOND THE SURFACE**

Copyright Roadscanners Oy 2013. All Rights Reserved.

# EXPERIENCES IN THE USE OF LASER SCANNERS AND GPR TECHNIQUES IN FROST DIAGNOSTICS ON ROADS AND STREETS






Timo Saarenketo, PhD Managing director Roadscanners Group







# EM TECHNIQUES IN NDT ROAD SURVEYS






### **3D GPR AND FROST ANALYSIS**





# 2D GPR FROST ANALYSIS IN WINTER

#### Detection of unfrozen water (ice lenses) in frozen ground






#### EXAMPLE OF GPR FROST ANALYSIS: RD 92, FINLAND

400 MHz GPR data

Ice in road structures



#### Laser Scanners (Lidars) in Frost Diagnostics






Copyright Roadscanners Oy 2013. All Rights Reserved



# Laser Scanner Information




# Laser Scanner Information: Rutting Diagnostics



ROADSCANNERS

Copyright Roadscanners Oy 2013. All Rights Reserved

# Integrated Analysis of 2D Laser Scanner, GPR and FWD data






Copyright Roadscanners 2013. All Rights Reserved


#### FROST ANALYSIS - RD 99 SWEDEN








#### FROST HEAVE DIAGNOSTICS – TRADITIONAL "TRANSITION WEDGE" PROBLEMS










Copyright Roadscanners Oy 2013. All Rights Reserve

#### **FROST HEAVE DIAGNOSTICS – BEDROCK POCKETS**








Copyright Roadscanners Oy 2013. All Rights Reserve

# 3D Laser Scanning Frost Heave Survey, Case: HW4, Rovaniemi






Copyright Roadscanners 2013. All Rights Reserve

# Frost Heave Diagnostics Findings:

Great Amount of Frost Heave Problems can be Related with Private Access Roads



SURFAC



# Frost Heave Diagnostics Findings:


#### Special problem: Glogged Private Acces Road Culverts







### Frost Heave Diagnostics Findings: Location of the Problems Caused By Glogged Culverts




#### Differential frost Heave at the End of Flooded Ditch








#### We have been Fixing Symptoms Instead of Reasons!






# FROST DIAGNOSTICS: DITCH BOTTOM TOO HIGH - CASE HW4






# FROST DIAGNOSTICS: POOR WATER FLOW IN DITCH, SHEET ICE AND FROST HEAVE












SURFACE

### Frost Diagnostics: Frost Heave in Inner Curves













#### **FROST HEAVE DIAGNOSTICS - ROAD WIDENING**






#### FROST HEAVE DIAGNOSTICS - OLD ROAD BENEATH



ROADSCANNERS

Copyright Roadscanners Ov 2013, All Rights Reserved.

#### FROST HEAVE DIAGNOSTICS - OLD STREET BENEATH








Copyright Roadscanners Oy 2013. All Rights Reserved



#### FROST HEAVE DIAGNOSTICS - TREES CLOSE TO ROAD





# THANK YOU

